


**Mounting instruction for beams Z 110 with miter cut**


Adaptor for beam Z 110 (big tension lock chamber)  
for assembly of 45° / 22.5° tension locks




Z 161/AS




Z 110



Z 963/L



Z 110



Z 953/L