


OCTA COUNTER

FABRIC



OCTANORM 


OCTACOUNTER FABRIC



Q 800.01


Aluminium/wood | base-set, silvergrey RAL 9006, displacement (45°) of the groove for flat welt
W 910 × D 446 × H 912
17.50 kg

Measurements for prints:
Front: W 905 × H 905 mm
Side: W 445 × H 905 mm





i The silicone edge has to be cut at a 45° angle.

FABRIC TENSION EXTRUSION 135°



M 1301.01

Aluminium | to fix fabric panels in connection with silicone welt
M 1313 M 1313 30 × 35 mm
6.55 kg | 6000 mm





INTERNAL CORNER CONNECTOR



M 1335.37

Steel | for connection of extrusions M 1300, M 1302, M 1309 and S 1605
0.06 kg





HINGE PLATE



Q 1801.33

Plastic | for mounting on threaded plate Q 1803
0.02 kg





THREADED PLATE



Q 1803.37

Steel | incl. 2 × fixing screw M5 and 1 × clamping screw M6 for mounting on fabric tension extrusion M 1300
0.05 kg



PARTS


OCTAcouter fabric

TRANSPORT BAG



Q 516.90

Nylon I navy blue with 2 castors and inner partitions for Q 800, with additional pocket for counter top and shelf boards
0.59 kg



OCTACOUNTER FABRIC,
FRONT VIEW




OCTACOUNTER FABRIC,
BACK VIEW



OCTACOUNTER FABRIC,
BACK- AND SIDE VIEW



OCTACOUNTER FABRIC,
FOLDED UP



OCTACOUNTER FABRIC
DETAIL HINGE PLATE



OCTACOUNTER FABRIC,
DETAIL FRAME CORNER



OCTANORM® Germany
Head Office
Raiffeisenstraße 39
70794 Filderstadt
T. +49 711 77003-0
F. +49 711 77003-53
info@octanorm.de
www.octanorm.com

EUROPE

OCTANORM® Belgium
T. +32 475 35 60 76
www.octanorm.be

OCTANORM® France
T. +33 1 8828 3932
www.octanorm.fr

OCTANORM® UK
T. +44 20 85 45 2945
www.octanorm.co.uk

OCTANORM® Hellas
T. +30 2310 79 6521
www.octanorm.gr

OCTANORM® Italia
T. +39 02 9645 1966
www.octanorm.it

OCTANORM® Nederland
T. +31 50 309 5133
www.octanorm.nl

OCTANORM® Polska
T. +48 22 773 0350
www.octanorm.pl

OCTANORM® Adria
T. +386 590 56301
www.octanormadria.com

OCTANORM® Espana
T. +34 930 019 424
www.octanorm.es

OCTANORM® Nordic
T. +46 8 621 6500
www.octanorm.se

OCTANORM® Russia
T. +7 495 565 7920
www.octanorm.ru

AMERICA

OCTANORM® North America
T. +1 770 7 32 1520
www.octanormna.com

OCTANORM® México
T. +52 55 5804 6325
www.octanorm.com.mx

OCTANORM® Argentina
T. +54 11 43 12 4000
www.octanorm.com.ar

AFRICA

OCTANORM® South Africa
T. +27 11 433 2010
www.octanorm.co.za

MIDDLE EAST

OCTANORM® Emirates
T. +971 4 340 6888
www.octanormemirates.net

AUSTRALIA

OCTANORM® Australia
T. +61 3 8773 8550
www.octanorm.com.au

ASIA

OCTANORM® Japan
T. +81 45 511 8144
www.octanorm.co.jp

OCTANORM® China
T. +86 512 6283 3336
www.octanorm.cn