



When using the dead lock cylinder W 514 at glass door W 501/W 502 the upright/extrusion must be countersunk according to the drawing!

TIMB73 E-000034-0201B-F03 - In Arbeit - 10.02.2009 ED / 07.02.2013 RE - 02/2013 shift